


Engine Failure

Tutorial for handling of an Engine Failure in the A320 family.



Note:

- After Liftoff follow the SRS (Speed Reference System) Signal
- In case of Engine Stall without ECAM Warning use the QRH Procedure
- Maximum TOGA Thrust available for a maximum of 10 Minutes!
- Level off for Acceleration only after Engine has been secured

Engine Fire: both Fire Bottles discharged

Engine Failure with damage: one Fire Bottle discharged

Engine Failure without damage: Master Switch Off

ONLY for Flight-Simulation!